



SOME GEOGRAPHICAL AREAS HAVE SPECIAL WIND CONDITIONS THAT CAN CREATE WIND INDUCED VIBRATIONS CAUSING A FATIGUE PROBLEM. NO METHOD HAS YET BEEN FOUND FOR PREVENTING OR DESTROYING LIGHTNING RODS. THESE CONDITIONS ARE UNIQUE AND CANNOT BE GUARANTEED AGAINST, AND ARE THE RESPONSIBILITY OF A LOCAL SITE ENGINEER.

WARNING: DO NOT INSTALL LIGHT POLE WITHOUT INTENDED LOADING.

TITLE: RD STEEL POLE CAP
 CATALOG: RD STEEL POLE CAP
 DWG NO: RD SPRING STEEL CAP GS
 SIZE: C
 SHEET 1 OF 1

2474 GROSSBORN HWY, WARREN, MI 48090
 PHONE: (586) 774-6005
 ORDERS@GENERALSTRUCTURESHQ.COM
 WWW.GENERALSTRUCTURESHQ.COM

GENERAL STRUCTURES INC.
AN IRVING-CLOUD COMPANY

DRAWN: L. GRUNIS	DATE: 9/12/2019
REVISION:	DATE:
QUOTE:	S.O. #
APPROVAL SIGNATURE:	APPROVAL SIGNATURE:

