



SOME GEOGRAPHICAL AREAS HAVE SPECIAL WIND CONDITIONS THAT CAN CREATE WIND INDUCED VIBRATIONS CAUSING A FATIGUE PROBLEM. NO METHOD HAS YET BEEN FOUND FOR PREVENTING OR REDUCING LIGHTNING STRIKE DAMAGE TO LIGHTNING PROTECTIVE DEVICES. THESE DEVICES ARE NOT TO BE GUARANTEED AGAINST, AND ARE THE RESPONSIBILITY OF A LOCAL SITE ENGINEER.

WARNING: DO NOT INSTALL LIGHT POLE WITHOUT INTENDED LOADING.

TITLE:
 CATALOG: SQ STEEL POLE CAP
 DWG NO: SQ SPRING STEEL CAP GS SIZE: C SHEET 1 OF 1

GENERAL STRUCTURES INC.
AN IRVING COMPANY

2474 BRUCEBANK HWY, WARREN, MI 48090
 PHONE: (586) 774-6005
 ORDERS@GENERALSTRUCTURESGS.COM
 WWW.GENERALSTRUCTURESGS.COM

| | |
|---------------------|---------------------|
| DRAWN: L. GRUNIS | DATE: 9/12/2019 |
| REVISION: | DATE: |
| QUOTE: | S.O. # |
| APPROVAL SIGNATURE: | APPROVAL SIGNATURE: |

